

SISPM1040-3166-L Release Notes

Date: Oct.8, 2019 Version: 8.40.1384

Overview

This release notes covers firmware version v8.40.1384 and MIB file for SISPM1040-3166-L.

Release Changes and Enhancements

- * CLI command changed:
- remove:
 - 1. snmp-server host test shutdown
 - 2. snmp-server host test no shutdown
- add:
 - 1.snmp-server host test trapmode disable
 - 2. snmp-server host test trapmode tcp
 - 3. snmp-server host test trapmode udp
- * AC-DC Power Input model LED Alarm light initial behaviors definition update.
- after switch powers on, if initial detected only AC or DC input, the alarm LED does not turn on.
- after switch powers on, if initial detected AC and DC input and System Ready, the AC or DC occurs power off that make alarm LED turn on.
- *Add soft reboot function.
- * Modify DMS mode behavior Mode options as below
- Disabled
- Enabled: high/low/mid/non
- * Add SNMP over TCP Feature Description.
- * Modify display method at SNMP OID.
- SNMP System Temperature:
 - *Separate out the Celsius and Fahrenheit for different OIDs.
 - *Only return a numerical value.(Do not change current OID attributes)
 - *Modify OID description.
- SFP/SFP+ variables:
- *Only return numerical value and not include the alpha description. (Do not change current OID attributes)
 - *Modify OID description.



- * Add "SNMP Server location" command.
- * Add Traffic monitor back to DMS.
- * Add Max Reboot Times, for PoE Auto Checking

Bugs fixed

- * Syslog function doesn't work.
- * Can't erase configuration about SNMPv3 community entry.
- * log message should show warm boot when rebooting switch via Web.
- * Can't set source mask to 255.255.255.255 or 255.255.255.0 in the SNMPv3 Community Configuration.
- * Fixed switch will crash issue.
- When NTP is enabled, but switch can't connect to NTP server and get time information.
- * There is no "Filter Port" description in the ACE Configuration Help page.
- * Correct some descriptions in HELP for ACE ARP Parameters.
- * The online help for "IP Address" / "Advanced Settings" contains non-existent features.
- * Can reset to factory default for MAC-Based VLAN.
- * S-Custom-Port can't send VLAN tag with TPID 88A8.
- * Can't enable Voice VLAN mode via Web UI.
- * Can't create 128 entries for IGMP profile.
- * Can't "clear" LLDP Statistics via Web UI.
- * Can't show "?" in the LLDP Neighbor Information via Web UI.
- * RMON Web and CLI of field don't match. (To remove community parameter in CLI)
- * Correct some typos for 802.1x log
- * Change "Battery-Power" group name to "DC-power" in Trap Event Severity.
- * Switch shows wrong 802.1X port status in Web UI.
- * Can't change UDLD message interval.
- * Can't input IPv6 address for sFlow receiver in the Web UI.
- * Can't reset SFlow port configuration to factory default.
- * There is an option "none" in sFlow Sampler type.
- * 802.1X MAC-based: Switch will crash when sending multiple MAC addresses to the port a period of time.
- * DHCP snooping doesn't work after reboot.
- * QoS WRR: get a wrong WRR percent via SNMP.
- * PoeChipsetRebootMode does not set via SNMP.
- * System CPU status shows 100% anytime.
- * ROMN: History status lost some data.
- * ROMN: History Buckets set to 60, but the History Sample Index displays 50 data.
- * ROMN: Statistics field record interface tx value.
- * SNMP:After send "no snmp-server community public" & "no snmp-server community privatec" command, the Read Community/Write Community field becomes garbled on Home -> SNMP -> Configuration page.



- * Non-Multicast MAC address can be set to two port number.
- * IP: Unable to add an IP Routes.
- * The admin account privilege level can be modified in the Web UI.
- * After IGMP snooping global mode is enabled, and send "save start config" and "reload warm", the vlan1 IGMP snooping mode will be disabled.
- * SNMP: n SNMPv3 Community Configuration, Source mask cannot be set via Web/CLI UI, and Web UI behavior is different from CLI.
- * SNMP: After sending "no snmp-server community public" & "no snmp-server community private" command, the Read Community/Write Community field becomes garbled on Home -> SNMP -> Configuration page.
- * unable to modify sFlow's Agent Configuration & Receiver Configuration via SNMPc.
- * CLI SFP information is different from Web UI.
- * LLDP: In Web UI, the LLDP-MED Neighbor Information -> Location information displays the "%XX" message.
- * execute the "Download config", the disk icon will flash.
- * LLDP: In Web UI, LLDP-MED Neighbor Information lost Inventory information.
- * Web: The switch can't be restarted when "non stop poe reboot" is executed via web.
- * CLI config-if mode entering "ptp" will crash.
- * CLI has "event group Link-Status", but Web UI don't.
- * System LED will not light up after boot.
- * DHCP server is automatically enabled after switch reboot.
- * Unable to send LLDP trap via TCP mode.
- * Unable to close PoE mode via Web UI.
- * PoE delay time can be set more than 0~300 sec.
- * ACL: ACE IPv6 Parameters "Hop Limit" setting is different from Help.
- * ACL: CLI's explanation of arp-tmac is different from Web UI.
- * QoS: Web's Shaper rates available setting is different from CLI.
- * QoS: In CLI, QCE's action parameters display "ingress-map" parameter.
- * Web UI-LLDP Neighbor Information cannot display "|".
- * System information does not show Temperature Degree.
- * 802.1x: forwarding 1024 different source address packets, Switch will crashes and reboot.
- * Port: Port Description can set the inconsistency of characters on Web/CLI/SNMP.
- * Multicast traffic leaks from one Private VLAN to another Private VLAN.
- * DMS: Upload Floor image, if filename contains a space, the file cannot be deleted.
- * After entering specific characters on SNMPv3 Community, Add New Entry will failed on Web UI.
- * WebUI-->IP Address-->Advanced Settings apply to delete ip interface, will shows error: "Cannot delete all interfaces."
- * SNMP: 10G port speed cannot set to 10G Full via SNMP.
- * Syslog: Import-Export cannot receive syslog.
- * https is disabled after reboot.
- * ACL: Port Policy ID can set the inconsistency of range on Web/CLI/SNMP.



- * Bug 20196 CLI log entries are truncated after 96 characters
- * When switch has only two VLAN Interfaces, it cannot be deleted.
- * Unable to see IP address assigned by DHCP Server in Web UI.
- * Unable to read the correct SFP information.
- * IGMP: After Join/Leave, when the specific query does not reach the RV number, igmp group will be cleaned up.
- * ICMP Ping ptt.cc will continue to display % Ready for new ping
- * The port-security command is executed on all ports in CLI, the CLI will hang, and Web & Ping & Telnet still work.
- * Port-Security: limit set to "1", only one mac connection will cause the switch shutdown.
- * Web: Unable to create a VLAN without an IP address.
- * SNMP: when setting Write community name and read community name are the same, unable to set behavior.
- * Firmware upgrade will cause switch crashes if switch can't download FW image via TFTP.

Known Limitations and Restrictions $\ensuremath{\mathrm{N/A}}$