



SMxxTAT2SA Release Notes

Date: Aug.27, 2019

Version: 1.02.1409

Overview

This release notes covers firmware version v1.02.1409 with MIB files for SM8TAT2SA, SM16TAT2SA, SM24AT2SA.

Release Changes and Enhancements

[Added]

- * Support Port Mirror and Cable Diagnostic features via API interface.
- * Add PoE force mode mechanism.
- * Add PoE Auto Power Reset event into Event Notifications.
- * Add PoE Soft Reboot feature.

[Bugs Fixed]

- *NTP: Unable to synchronize time with Ubuntu NTP server.
- *API : The switch shall not accept the value of Maxpwr per port larger than 30Watts.
- * API: Get Mac Based Vlan config Response mac-based_vlan -> minus sign needs to be changed to underline/
- * API: When Set Port Config, it's recommended that the "enable" field should not be set by user. If the setting is wrong, speed_mode will also remain unchanged.
- * API: When Set PoE Config to the non-existing port number, switch will change the PoE Mode with the port number to null /Maximum Power to 0.
- *Can't get gateway IP from DHCP sever if repeating to enable/disable DHCP client mode on switch.
- * Web: Select VLAN Port Status page, the information is wrong and CLI shows error message.
- * VLAN: Comparing CLI output with web UI, the CLI show vlan status misses VLAN User information.
- * Port: Only forward 10000 bytes length size packets, but statistics Tx/Rx size counter provides a 16383 bytes field.
- * API: Get IP Address function can't obtain the switch DHCP IP.
- * DMS Diagnostics result is wrong when port is link down.
- * Even the account was deleted, but it's restored after reset.
- * Syslog: Port management->Port Configuration, configure port description then click apply, switch ping reply will timeout and show link show link/up log.



Transition Networks
10900 Red Circle Drive
Minnetonka, MN 55343
www.transition.com

Known Limitations and Restrictions

* Jumbo frames are forwarded correctly, but are counted in the “1519-max” frame-size buckets and also counted in the “Oversize” buckets.