

Transition Networks 10900 Red Circle Drive Minnetonka, MN 55343 www.transition.com

SM24TBT2DPA Release Notes

Date: Oct.19, 2020 Version: vB6.54.3576

Overview

This release notes covers firmware version vB6.54.3576 and MIB file for SM24TBT2DPA.

Release Changes and Enhancements

[Add and Change]

- *Support TLV IEEE802.3 MAC/ PHY configuration/status in LLDP packets.
- * API + Device list table requirement.
- * Add RADIUS and TACACS Key encryption on Show Running Config.
- * Modify name "Non-stop PoE" to "Always-On PoE" and add "Always-On PoE" in mib.
- * Add Timeout expected behavior
- * Add MAC range to identify LED lighting device.

[Bugs Fixed]

- * PoE: After PoE Overload, the PD shows "link down", but PoE LED still is orange.
- * PoE: PoE Delay time is not accurate.
- * PoE: PoE Auto Checking startup Time is not accurate.
- * PoE: PoE Auto Checking Interval Time is not accurate when interval-time is 120 seconds.
- * PoE: When PoE Auto Checking Reboot Time is functioning, the PD supply is not stable.
- * CLI: Correct the Radius/TACACS server key command description.
- * CLI: Unnecessary poe power limit command in PoE function.
- * API: get_port_config and set_port_config returns media is "cooper"
- * API: set_mirror_config does not exactly apply configuration to the switch.
- * API: The reply JSON format of "device_list_table" has no pause.
- * After Reload Defaults, the WebUI-DHCP Server VLAN Range does not clear.
- * Reflash the WebUI, the Timeout setting will return to Startup Config setting.
- * SNMP: unable to get information of sm24tbt2dpaPoeStatusTable oid.
- * PoE: After Power budget exceeded and then link down PD, the PoE LED bright orange.
- * Web: After reload default, the web timeout will not return to the default value.
- * Web: PoE Status help page description is wrong.

Known Limitations and Restrictions



Transition Networks 10900 Red Circle Drive Minnetonka, MN 55343 www.transition.com

- 1. The switch is not allowed to downgrade to firmware versions older than vB6.54.3476 due the PoE MCU firmware was upgraded.
- 2. Get wrong status when getting firmware upgrade status in API.