

Firmware Release Notes

NTC-227



Copyright

Copyright© 2021 NetComm Wireless Limited. All rights reserved.

The information contained herein is proprietary to NetComm Wireless. No part of this document may be translated, transcribed, reproduced, in any form, or by any means without prior written consent of NetComm Wireless.

Trademarks and registered trademarks are the property of NetComm Wireless Limited or their respective owners. Specifications are subject to change without notice. Images shown may vary slightly from the actual product.



Note – This document is subject to change without notice.

Document history

This document covers the following products:

NTC-227

| VER. | DOCUMENT DESCRIPTION | DATE |
|-------|--------------------------|---------------------------------|
| v1.00 | Initial document release | 23 rd September 2021 |

Table i. - Document revision history

Contents

| | |
|----------------------------|---|
| Release information | 4 |
| Release history | 4 |
| v2.1.18.0 | 4 |
| New features | 4 |
| Enhancements | 4 |
| Upgrade instructions | 4 |

Release information

| ITEM | DETAILS |
|-------------------------|----------------------------------|
| Product code | NTC-227 |
| Router firmware version | 2.1.18.0 |
| Development status | Official |
| Firmware file name | ntc_227_2.1.18.0-signed.cdi |
| MD5 code | 106B88B110D487A530F9CEDA6E6410DA |
| Date | 23 rd September 2021 |






Release history

v2.1.18.0

New features

 None.

Enhancements

-  User Guide has been updated (TT#42605)
-  Various web interface related fixes (TT#42652,42654,42662,42615,42634,42664)
-  Modernized some terminology (TT#42702)
-  Corrected the IPv6 address display when PDP is set to IPv4v6 / IPv6 (TT#42732)
-  Fixed an issue that could occur when upgrading the module firmware (TT#42760)

Upgrade instructions

Please refer to the steps described in the **NTC-227 Firmware Upgrade Guide.pdf** (doc no. FI01390) document.