



ION C3110 Release Notes

Date: May 30, 2011

Version: 1.1.0

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues, and known limitations for the ION C3110 product.

Management of the ION C3110 is available when installed in an ION219 chassis along with an IONMM management module. Management information is available through a web browser, Command Line Interface (CLI) via the IONMM, or via SNMP.

Requirements:

Firmware version 1.1.0 and these release notes apply to the following products:

- C3110-10xx

New Features and Enhancements:

The following list is new features and enhancements for version 1.1.0 of the ION C3110 products.

- Command Line Interface help files have received updates.

Fixes:

- On the SFP version, C3110-1040 with an SFP module inserted, the converter now properly displayed in the management interface.

Known Feature Limitation:

The following list is currently known issues for the ION C3110 products.

- Auto negotiation and Loopback should not be enabled at the same time.
- Fiber link status is incorrectly displayed as Link-Up, when a 100Mbps device is connected to the 1000Mbps fiber port.
- When copper is not connected to the 1000Base-T RJ-45 port, the speed and duplex status is not displayed properly.

Related Documentation:

- ION C3110 Install Guide (33417)
- ION219-A Install Guide (33412)
- IONMM Install Guide(33420)