

=====

Software Release Note

=====

RELEASE DATE: 07-Nov-2011

FIRMWARE VERSION: V1.10

KERNEL VERION: V3.59

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:

Note!! The following Known Issues have been fixed in this release of firmware.

1. Add TACACS+ function.
2. Add IP Subnet function for IP security.
3. Modify the Rate Limit function from scale option e to keying value.
4. Fix OID counter fail bug.
5. Fix rate limit fail bug.

KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

KNOWN ISSUES:

Note!!The following Known Issues will fix in the further release of firmware.

N/A

Software Release Note

RELEASE DATE: 07-Sep-2010
FIRMWARE VERSION: V1.10
KERNEL VERION: V3.21

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:

Note!! The following Known Issues have been fixed in this release of firmware.

Modify Max MTU to 1526 bytes for Q-in-Q.

KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

Software Release Note

RELEASE DATE: 19-July-2010
FIRMWARE VERSION: V1.10
KERNEL VERION: V3.15

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:

Note!! The following Known Issues have been fixed in this release of firmware.

1. Modify description " IP binding" help file..
2. Fixed link status error at :
 - a). When DUT force speed at 1000M can link up with Ixia/Smartbits force speed at 100M.
 - b). After disable and enable on one port, that port always links at 10M/half.

KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

Software Release Note

RELEASE DATE: 14-May-2010
FIRMWARE VERSION: V1.09
KERNEL VERION: V3.03

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:

Note!! The following Known Issues have been fixed in this release of firmware.

Add QinQ function in this version.

KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

=====
Software Release Note
=====

RELEASE DATE: 22-Jan-2010
FIRMWARE VERSION: V1.09
KERNEL VERION: V2.77

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:

Note!! The following Known Issues have been fixed in this release of firmware.

For X-ring:

1. Modify X-ring BPDU DA Mac address from 01-80-C2-00-00-0E to 01-80-C2-00-00-09.
2. Increasing stability of X-ring, we Modify and enhance the X-ring BPDU priority, so that CUP can process X-ring BPDU first than other packets at the same time.

KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

=====
Software Release Note
=====

RELEASE DATE: 13-Oct-2009
FIRMWARE VERSION: V1.08
KERNEL VERION: V2.50

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:

Note!! The following Known Issues have been fixed in this release of firmware.

Modify the Rate Limit function from keying value to scale option.

KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

KNOWN ISSUES:

Note!! The following Known Issues will fix in the further release of firmware.

N/A

=====

Software Release Note

=====

RELEASE DATE: 25-Sep-2009
FIRMWARE VERSION: V1.08
KERNEL VERION: V2.44

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:

Note!! The following Known Issues have been fixed in this release of firmware.

Add prevention in firmware structure to prevent user clicked "Apply" multiple times cause the Ring loop.

KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

KNOWN ISSUES:

Note!! The following Known Issues will fix in the further release of firmware.

N/A

=====

Software Release Note

=====

RELEASE DATE: 02-Sep-2009
FIRMWARE VERSION: V1.08
KERNEL VERION: V2.30

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:

Note!! The following Known Issues have been fixed in this release of firmware.

Fixed UDP packets couldn't forward to Gateway correctly cause CPU hang.

.
KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

KNOWN ISSUES:

Note!!The following Known Issues will fix in the further release of firmware.

N/A

=====
Software Release Note
=====

RELEASE DATE: 28-July-2009
FIRMWARE VERSION: V1.07
KERNEL VERION: V2.06

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:

Note!! The following Known Issues have been fixed in this release of firmware.

Fixed the compatible issue with TN-GLC-T SFP.

.
KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

KNOWN ISSUES:

Note!!The following Known Issues will fix in the further release of firmware.

N/A