



SM8TAT2DPA Release Notes

Date: Mar.22, 2013

Version: 2.00

Overview

This release notes covers firmware version v2.00 for SM8TAT2DPA.

Release Changes and Enhancements

Firmware Version: v2.00

[Fixed]

- =====
- * SNMPv3 Trap Host Configuration display abnormal after executed SNMP command by CLI.
 - * ACL function doesn't work when receiving ARP packets.
 - * Mib: To change term Passwd to Password in events.

Firmware Version: v1.54

[Fixed]

- =====
- * Timed out to get next MIB on OID "ExportOrImport"
 - * Press "Save" on SNMP setting page will show error message or web UI error.
 - * Vlan trunk port function doesn't work after reboot.
 - * To use some router with external device function, the function will failed when enable vlan function.

Known Limitations and Restrictions

Update firmware version from v1.39 -> v1.54 -> v2.00, v1.39 is NOT able to update to v2.00 directly