



ION C3110 Release Notes

Date: September 12, 2011

Version: 1.2.0

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues, and known limitations for the ION C3110 product.

Management of the ION C3110 is available when installed in an ION219-x chassis along with an IONMM management module. Management information is available through a web browser, Command Line Interface (CLI) via the IONMM, or via SNMP.

Requirements:

Firmware version 1.2.0 and these release notes apply to the following products:

- C3110-10xx

New Features and Enhancements:

The following list is new features and enhancements for version 1.2.0 of the ION C3110 products.

- Cold start-up time has been improved. The ION chassis, power supplies, and slide-in-cards will boot up and be ready for SNMP based management in less than half the time required with the previous version

Known Feature Limitation:

The following list is currently known issues for the ION C3110 products.

- Fiber link status is incorrectly displayed as Link-Up, when a 100Mbps device is connected to the 1000Mbps fiber port.
- When copper is not connected to the 1000Base-T RJ-45 port, the speed and duplex status is not displayed properly.
- A few display and command inconsistencies are noticeable in the CLI interface as compared to the Web Management interface; these will be addressed in the next release.

Related Documentation:

- ION C3110 Install Guide (33417)
- ION219-x Install Guide (33412)
- IONMM Install Guide(33420)