



---

## SISPM1040-3166-L Release Notes

**Date: Feb.3, 2020**

**Version: 8.40.1565**

---

### Overview

This release notes covers firmware version v8.40.1565 and MIB file for SISPM104-3166-L

### Release Changes and Enhancements

#### [New Features & Changes]

---

- \* Add a field to show Aggregated Bandwidth information on Link Aggregation feature.
- \* Add System Name on Tab of Web browser.
- \* Change port-security command description
- \* Restore the traffic monitor function as a standard feature.
- \* Add Click Save Button when Save Start Button on Web UI.
- \* Password encoding enhancement.
- \* Add PoP “Traffic Monitor feature is only available on master switch.” Message on All Supported DMS Switches Web UI.
- \* Modify topology view right side function key design.

#### [Bugs Fixed]

---

- \* MEP: when cPriority is set to 7, it will cause the mep state in the mep instance to fail.
- \* The switch supply power to PD device during startup.
- \* CLI: Error message appears during startup.
- \* Web: LACP key error message is wrong.
- \* CLI: port-security description is wrong

#### Known Limitations and Restrictions

1. The password encoding is improved in the firmware version v8.10.1565, user will be unable to login if downgrading the switch to older firmware versions or loading an old configure file in new firmware unless making Factory default.
2. ERPS: UP MEP is not supported for sub-ring