

**SISPM1040-362-LRT Release Notes****Date: May 21, 2026****v7.20.0260**

---

**Overview**

These release note covers firmware version v7.20.0260 for model SISPM1040-362-LRT.

**Bugs Fixed**

- Unable to establish ERPS ring between 3.65 and 4.4 series devices.

**Known Limitations**

- Rapid Ring roles cannot be returned to Disable using the Web GUI. The roles can be disabled using the CLI command interface.
- Web timeout has issue with timeout set greater than 10 minutes.
- Customers updating from v7.10.2544 should contact Lantronix Tech Support for assistance with the upgrade as it requires multiple steps to v7.20.0206.