



SISPM1040-384-LRT-C Release Notes

Date: Dec.29, 2018

Version: 7.10.1656

Overview

This release notes covers firmware version v7.10.1656 for SISPM1040-384-LRT-C and SISPM1040-384-LRT-NY.

Release Changes and Enhancements

[Added]

=====

- * SSL certificates
- * Support 128 characters for Port Description field.
- * Add Port-Security sticky mac.
- * DMS Map View - Add upload Google map API key function.
- * Add NTP Time Sync Interval.
- * Add SCP feature.
 - Download/upload switch startup config
 - Upgrade switch's firmware
 - Upgrade PoE controller MCU PD69200 code

[Bug Fixed]

=====

- * MIB OID is shifted due to add PoE Firmware Version OID.
- * Device's http port number can be modified in the topology view, but can't be modified in the DMS device list page.
- * Can't get SFP info via SNMP
- * CLI: "clock set" command effects the switch automatically reboot.
- * When configuring MSTP, switch will lose VLAN connection after reboot.
- * Sometimes switch can't send STP BPDU packets when STP is enabled.
- * Parent node shows between two DMS switches, even gateway already changed to correct one on all DMS switches.
- * Topology view is wrong, and parent node shows between two DMS switches.

Known Limitations and Restrictions

N/A