



SISPM1040-384-LRT-C Release Notes

Date: May.20, 2021

Version: 7.20.0075

Overview

This release notes covers firmware version v7.20.0075 and MIB file for SISPM1040-384-LRT-C

Release Changes and Enhancements

[New Features & Changes]

- =====
- * Switch reboot according to DI input.

[Bugs Fixed]

- =====
- * DDM information are not updated.
 - * PoE force mode cannot be saved.
 - * DIDO: After triggering DI reboot system event, server may not receive syslog event.
 - * PMD auto negotiation advertised capability information is wrong in the LLDP packet of fiber ports.
 - * Port can't link up when TN-EOT-CO and TN-EOT-RT copper module is inserted after rebooting switch or changing mode from force 1000M to auto.

Known Limitations and Restrictions

N/A