PacketBand 2RU Chassis Release Notes
Date: July 25, 2013
Version: Vb8.58

Overview
This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the PacketBand 2RU chassis product.

Management of the PacketBand is available using DbManager.

Requirements:
Firmware version Vb8.58 and these release notes apply to the following products:
- PB-TDM-8-AC
- PB-TDM-8-DC
- PB-TDM-16-AC
- PB-TDM-16-DC
- PB-TDM-32-AC
- PB-TDM-32-DC

New Features and Enhancements:
- None

Bug Fixes:
- Enables use of T1 signal on the external clock ports of the terminal card.

Related Documentation:
- PacketBand User Manual