SISPM1040-582-LRT Release Notes
Date: September 3, 2026
vB7.20.0269

Overview

These release note covers firmware version vB7.20.0269 for model SISPM1040-582-LRT.

Bugs Fixed

- Ring to Ring backup path fails to transition to forwarding when active ring to ring switch loses power.
- Network loop occurs when the active switch is restarted after configuring a ring-to-ring topology.

Known Limitations

- Rapid Ring roles cannot be returned to Disable using the Web GUI. The roles can be disabled using the CLI command interface.
- Web timeout has issue with timeout set greater than 10 minutes.
- Customers updating from v7.10.2544 should contact Lantronix Tech Support for assistance with the upgrade as it requires multiple steps to v7.20.0206.