===
Software Release Note
===
RELEASE DATE: 18-Jul-2011
FIRMWARE VERSION: V1.08
KERNEL VERSION: V3.55

FIRMWARE CHANGES AND ENHANCEMENTS:

N/A

MODIFICATIONS:
Note!! The following Known Issues have been fixed in this release of firmware.

1. Fixed SFP initial negotiation issue on combo port when DUT reboot.

KNOWN RESTRICTIONS AND LIMITATIONS:

N/A

KNOWN ISSUES:

Note!!The following Known Issues will fix in the further release of firmware.

N/A