S3240 Release Notes
Date: February 23, 2012
Version: 1.0.1

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the S3240 product.

Management of the S3240 is available using a web browser or Command Line Interface (CLI) via the local USB port or telnet of the S3240 or via SNMP.

Requirements:

Firmware version 1.0.1 and these release notes apply to the following products:
- S3240

New Features and Fixes:

The following list is a list of new features and bugs fixed in firmware version 1.0.1.
- Corrected issue where management VLAN was lost after several reboots of the product.
- Updates to support Microsoft IE 9
- SSH updated to support "Diffie-Hellman Group14 SHA1" key exchange
- Minor CLI improvements
- Additional user name and password settings

Known Feature Limitations:

The following list is currently known issues for the S3240.

- Web interface and CLI are different for FNG alarm time and FNG reset time
- RADIUS server secret is not backed up in configuration backup & restore

Related Documentation:
- S3240 User Guide (33459)
- ION Command Line Interface Reference Guide (33474)

MIBs:
- S3240_MIB.zip file