INDURA Release Notes
Date: September 8, 2014
Version: 1.7.4.16

Overview
This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the INDURA product family.

Management of these products is available using Converge™ EMS, SNMP, Web or Command Line Interface (CLI) locally or via Telnet.

Requirements:
Firmware version 1.7.4.16 and these release notes apply to the following products:
- IND3280-L
- IND3280-H
- IND3284-L
- IND3284-H

New Features and Enhancements:
The following is a list of new features and enhancements for version 1.7.4.16
- Syslog messages to indicate when a user attempts to log in via CLI, Web or console
- Syslog messages on add/remove of authorized users

Fixes in 1.7.4.16
- Fix for issues with SSH and TACACS+ where session exits were handled incorrectly

Known Feature Limitations:
The following is a list of currently known issues for the S3280.
- MEPs do not work over ports using link aggregation
- L2CP settings are in the CLI only and not Web interface

Related Documentation:
Please visit the specific product web page for detailed documentation
- Install Guide
- User Guide
- CLI Reference Guide

MIBs:
- TNMIBs_1.7.4.16.zip file