SISPM1040-384-LRT-B Release Notes
Date: Jul.20, 2016
Version: 1.24_k10.08

Overview

 This release notes covers firmware version v1.24_k10.08 for SISPM1040-384-LRT-B.

Release Changes and Enhancements

1. Add Sflow.
2. Add SNTP page in Web.
3. Disable PoE legacy support.
4. Fix "button in IP configuration page became gray" issue.
5. Add port alias into Trap and Syslog.
6. Fix VLAN configure fail issue.
7. Fix MRP enabled error message after MRP config save
8. Fix configuration upload error message after config restore
9. Add 1G option for SFP (TN-GLC-T).
10. Add UI for changing managed VLAN.
11. Correct the counters of PoE auto-ping function.
12. Fixed MODBUS TCP issue.

Known Limitations and Restrictions
N/A