SM24TAT4XA Release Notes
Date: May.19, 2017
Version: v3.41

Overview

 This release notes covers firmware version v3.41 for SM24TAT4XA.

Release Changes and Enhancements

1. Update Dropbear SSH version to 2016.74.

2. [Fixed Bugs]

    a. Can't get a correct value for IP-MIB::ipAdEntIfIndex.
    b. All original dynamic MACs with dynamic type are changed to static type when voice VLAN function is enabled.
    c. The Index ID's of the active Slave Switches should be deactivated when user's privilege level is lower than Single IP group.
    d. There is a spelling mistake in the Single IP Information Help page.
    e. The LLDP Neighbor Feature shows wrong IPv6 addresses.
    f. sFlow: fixed CPU load to 100% and stop to send sflow sample issue.
    g. SNMP function doesn't work, when using telnet to access switch, then login/logout switch via web.
    h. Switch cable can't link up when using 4 wire cable in Auto Negotiating Speed mode.
    i. There is a typo in the Easy Port Configuration Help.
    j. Switch reboot once receive DHCP offer/ack packets over 576 bytes.
    k. Static Trunk configuration is missing after export/import config file.
    l. IGMP Snooping: Router port setting is missing after export/import config file.
    m. STP port status always show forwarding status when using SNMP to get MIB dot1dStpPortState.Add an API for reading PoE temperature.
    n. Add an API for CPU load and RAM/Flash Memory (free/used)

Known Limitations and Restrictions

  N/A