Switch Manager TNMobileApp Release Notes
Date: 01/24/2020
Version: 2.1.0

Overview
This release note covers the requirements, important notes, and known limitations for the TN Mobile App used with the SESPM1040-541-LT-xx Series Self-Enclosed Managed Hardened Gigabit Ethernet PoE++ Switch.

The App can be used on a mobile phone or tablet equipped with an Android-based Operating System, NFC reader and BLE capability.

Requirements:
Mobile App Version 2.1.0 and these release notes apply to the following products:
- • SESPM1040-541-LT-AC-xx (beginning with firmware version 2.1.0.3)
- • SESPM1040-541-LT-PD (beginning with firmware version 2.1.0.3)

New Features or Enhancements in this Release:
- Within **Initialize**, the *Configure* tab now supports Management VLAN and VLAN Port Number fields.
- Within **Initialize**, the *Configure* tab fields are now validated. A warning message specifying the invalid field will appear when you try to save an invalid entry.
- Within **Initialize**, the *Files* tab has been removed. It will be re-added with later development.
- Within **Troubleshoot**, the *Password* field characters are now hidden.
- Under **Troubleshoot**, added *Set IP Address* button functionality. The button can now be used to set the IP Address, Subnet Mask, and Default Gateway.
- Under **Troubleshoot**, the Switch Commands box now supports longer commands such as restore and upgrade of switch firmware.
- Under **Troubleshoot**, the speed of switch command operation has been improved.
- Under **Troubleshoot**, the font has been changed to improve readability of switch command output.

New Features in Development:
The following is a list of new features and enhancements in development:
- Within **Initialize**, in the *Transfer* tab, the *Export* button is a placeholder for future enhancements.

Related Documentation:
- • SESPM1040-541-LT-xx Self-Enclosed Managed Hardened Gigabit Ethernet PoE++ Switch Install Guide (33772)
- • SESPM1040-541-LT-xx Series Switch Manager Mobile App Guide (33789)