SISGM1040-284-LRT Release Notes
Date: Sep.8, 2020
Version: 7.10.2667

Overview

This release notes covers firmware version v7.10.2667 and MIB file for SISGM1040-284-LRT.

Release Changes and Enhancements

[New Features & Changes]
==
* Add RADIUS and TACACS Key encryption on Show Running Config.
* Add Unified API support
* Expected Web GUI timeout
* Modify System Information Name display
* Add Click Save Button when Save Start Button on Web UI.

[Bugs Fixed]
==
* API: Setting IP address/dhcp/fallback/ip via api/set_ip_address, the interface does not has fallback timer.
* Web: Setting radius/tacacs config(key is not encryption)and reboot, the CLI will show Error: HTTPD cache has no valid entry!
*Web: Setting radius/tacacs config(key is encryption), the CLI will show Error: HTTPD cache has no valid entry!.
*API: get_port_config and set_port_config returns media is "cooper"
*API: set_mirror_config does not exactly apply configuration to the switch.
*API: The reply JSON format of "device_list_table" doesn't have the pauses.
* API:Setting Vlan Config via API, the allowed_vlan set to "1-10,400-4094",but get "1-10%2C400-4094" via API.
*API:(TN)Setting ip address/dhcp/fallback/ip via api/set_ip_address, but the interface does not has fallback timer.
* CLI: redundant "show dhcp" command executable.
* Switch cannot issue DHCP IP other than VLAN 1.
* Web: Modifying the System name will change to the Model Name on the left tab

Known Limitations and Restrictions
        N/A