SISPM1040-3248-L3 Release Notes
Date: August 17, 2023
Version: 8.10.0086

Overview

This release note covers firmware version 8.10.0086 and Mib files for SISPM1040-3248-L3.

Release Changes and Enhancements

- N/A

Bugs Fixed

- Rapid Ring configuration is not saved / applied after reboot of switch.
- Memory leak occurs during SNMP MIB walk.
- Ports 25-32 don't support PoE and should not show on PoE status page.

Known issues

- None