SISPM1040-362-LRT Release Notes
Date: Mar.30, 2018
Version: 7.10.1377

Overview

This release notes covers firmware version v7.10.1377 for SISPM1040-362-LRT.

Release Changes and Enhancements

Bug fixed: Switch will send UDP broadcast packets with link local address to port 9527, even if DMS has been disabled.

Known Limitations and Restrictions
N/A