SM12DP2XA RevA Release Notes
Date: December 6, 2024
Version: v7.20.0206

Overview

These release note covers firmware version v7.20.0206 and MIB files for model SM12DP2XA.

Bugs Fixed

- Percepxion server now shows error message when wrong firmware is uploaded
- Fixed incorrect voltage value on Percepxion server telemetry page
- Resolved timing issue with Percepxion telemetry exchanges

Known Limitations

- Rapid Ring roles cannot be returned to Disable using the Web GUI. The roles can be disabled using the CLI command interface.
- Web timeout has issue with timeout set greater than 10 minutes.
- Customers updating from v7.10.2544 should contact Lantronix Tech Support for assistance with the upgrade as it requires multiple steps to v7.20.0206.