**SM12DP2XA Release Notes**
**Date: March 10, 2026**
**Version: v7.20.0254**

## Overview

These release note covers firmware version v7.20.0254 for model SM12DP2XA.

## New Features

- Disabled TLS 1.0 and 1.1; active version is TLS 1.2. Ensure web browser is up to date.

## Bugs Fixed

- Press RESET button to default will display error message on CLI.
- Switch is accepting HTTP requests on port 80 even after creating ACL rule to deny HTTP traffic.

## Known Limitations

- Rapid Ring roles cannot be returned to Disable using the Web GUI. The roles can be disabled using the CLI command interface.
- Web timeout has issue with timeout set greater than 10 minutes.
- Customers updating from v7.10.2544 should contact Lantronix Tech Support for assistance with the upgrade as it requires multiple steps to v7.20.0206.