SM12DP2XA Release Notes
Date: May 29, 2025
Version: v7.20.0230

Overview

These release note covers firmware version v7.20.0230 for model SM12DP2XA.

New Features

- None

Bugs Fixed

- Fixed capitalization in Telemetry Log level and Log details
- Fixed IP routing not working after Save Config and Reboot
- Can now establish SSH connection via SecureCRT
- Fixed bug preventing SSH connection via SolarWinds NCM
- Fixed bug with Copper SFP module (TN-SFP-T-MG) Link LED lighting up when no cable is connected and data forwarding fail when cable connected.

Known Limitations

- Rapid Ring roles cannot be returned to Disable using the Web GUI. The roles can be disabled using the CLI command interface.
- Web timeout has issue with timeout set greater than 10 minutes.
- Customers updating from v7.10.2544 should contact Lantronix Tech Support for assistance with the upgrade as it requires multiple steps to v7.20.0206.