SM24DP4XA Release Notes
Date: Jan.8 2020
Version: 7.10.2341

Overview

This release notes covers firmware version v7.10.2341 for SM24DP4XA

Release Changes and Enhancements

[New Features & Changes]
==
* Add Click Save Button when Save Start Button on Web UI.
* Add PoP "Traffic Monitor feature is only available on master switch." Message on All Supported DMS Switches Web UI.
* Improve Password Encoding feature.
* modify topology view right side function key design.

[Bugs Fixed]
==
* CLI: redundant "show dhcp" command executable.
* LLDP: Management Address value of the LLDP packet is MAC, not IP address.
* NTP: 4 ~5 days after the switch is started, the switch does not actively send NTP packets to synchronize the time.

Known Limitations and Restrictions
1. The copper SFPs TN-GLC-T and TN-GLC-T-MG are not supported on the 10G SFP+ slots.