

Firmware Release Notes

4G LTE Cat M1/NB1 Industrial IoT Serial Modem



Copyright

Copyright© 2021 NetComm Wireless Limited. All rights reserved.

NetComm Wireless Limited was acquired by Casa Systems, Inc. a Delaware company on 1 July 2019. The information contained herein is proprietary to Casa Systems, Inc. No part of this document may be translated, transcribed, reproduced, in any form, or by any means without prior written consent of Casa Systems, Inc.

Trademarks and registered trademarks are the property of NetComm Wireless Limited or their respective owners. Specifications are subject to change without notice. Images shown may vary slightly from the actual product.



Note – This document is subject to change without notice.

Document history

This guide covers the following products:

NetComm Wireless - 4G LTE Cat M1/NB1 Industrial IoT Serial Modem

VER.	DOCUMENT DESCRIPTION	DATE
v1.0	Initial document release	17 August 2018
v1.1	Updated for v2.7.0	13 September 2018
v1.2	Re-issued for v2.7.0 with more detail and newly discovered known issue	19 September 2018
v1.3	Updated for v3.3.1	2 May 2019
v1.4	Updated for v3.3.3	22 November 2019
v1.5	Updated for 3.3.9	6 April 2020
v1.6	Updated for 3.4.1	10 June 2020
v1.7	Updated for 3.5.7	19 October 2020
v1.8	Updated for 3.6.0	15 January 2021
v1.9	Updated for 3.7.1	24 March 2021

Table i. - Document revision history

Release information

ITEM	DESCRIPTION
Product Model	NTC-100-01
Module firmware version	BG96MAR02A010M1G_O
Application firmware version	3.7.1
Status	Official
File name for OTA update	NTC100.3.7.1.bin.signed MD5: 08b1b0ef6d35c99ddf8b89f31b09e43a
File names for local PC update (Required for Local PC update if base firmware is older than v3.3.1)	NTC100.bin MD5: 57c9d7c19be5892b2c1d7dbff6972332 NTC100.signature MD5: 3eef11f37a07a572b4a75c42d4b64e64] oem_app_path.ini MD5: 82201f76f99c7e3e5696cab1b017848f

Release history

v3.7.1

Enhancements

ISSUE ID	DESCRIPTION
41533	Implemented the file system's backup and restore feature
41977	AT+PDP_TYPE option list has been updated

v3.6.0

Enhancements

ISSUE ID	DESCRIPTION
40967	Fixed UART max buffer limit issue.
40968	Improved AT+QICSGP command try mechanism to ensure the APN profile parameters are correctly set on the module.

v3.5.7

Enhancements

ISSUE ID	DESCRIPTION
41228	Extended the application bootup time to allow module to sync up with the application when device is powered on.
40978	Improved IP handling mechanism on the application side.

v3.4.1

Enhancements

ISSUE ID	DESCRIPTION
40644	Improved PDP connection manager to be more reliable and faster for multi APN configuration

v3.3.9

Enhancements

ISSUE ID	DESCRIPTION
39540	Fixed a bug in which enabling CEREGR URC prevented PPP dial from the serial port.
39541	Implemented transporting of URC message received from the module to the Serial port.

Enhancements

ISSUE ID	DESCRIPTION
38222	Fixed an issue where an error was returned when the "get settings" SMS command was sent and the reply contained more than 160 characters.
38223	Fixed an issue where the "1234execute pdpcycle" command returned an error despite successful execution.

New features

ISSUE ID	DESCRIPTION
22516	LWM2M Client implemented
22508	Log storage and export implemented
22509	Added at+all_config? command to display all current configuration
24843	Application filename now includes version number
22532	Added the ability to export and download the default and current configuration files

Enhancements

ISSUE ID	DESCRIPTION
24380	Fixed an issue where the device may stop attempting to connect if the first APN from a multiple APN list fails to connect.
22517	Improved serial throughput in PPP mode
22522	Improved PPP mode dialling

v2.9.1 (beta)

Enhancements

ISSUE ID	DESCRIPTION
22515	Implemented ability to enable/disable login authentication
22514	Updated Status message to show RSRP.
22511	Modified AT+SERVER command so that in PAD Server mode, Server IP address configuration is not mandatory.
38108	Fixed a force reconnect issue
22512	Implemented TCP kick off.
22521	Implemented DCD pin control commands.
24839	"set server" SMS command now accepts a hostname, not just an IP address.

Enhancements

ISSUE ID	DESCRIPTION
24373	SMS notifications are now sent when the Module firmware is upgraded successfully.
24357	In PAD server mode, TCP/UDP connections are now established when pdp_type=IPV4V6
24381	Improved the handling of the “get ping” SMS command.

Known issues

ISSUE ID	DESCRIPTION
24380	If the first APN in a multiple APN list fails to connect, the device doesn't re-attempt with the second APN.
24839	The 'set server' SMS command does not accept hostnames.