

## xFMFF1xxx-2xx Documentation Release Notes


Date: April 21, 2014

### Overview

This release note addresses known issues for the xFMFF1xxx-2xx product manuals.

### Known Documentation Issues

- Change ports layout text and graphic per C140301 (see below).
- Remove the obsoleted "622 Mb/s cable speed" models for manual PNs 33173 and 33174.
- Replace the obsolete SPS-1872-SA and SPS-1872-PS with PN SPS-2460-SA and SPS-2460-PS for manual PN 33174.



### Related Documentation

- CFMFF1xxx-2xx User Guide (PN 33173 Rev. U)
- SFMFF1xxx-2xx User Guide (33174 Rev. S)

These manuals will be updated with the relevant changes at the next major firmware release.