

=====

**Software Release Note**

=====

**RELEASE DATE:** 09-Aug-2010  
**FIRMWARE VERSION:** V1.07  
**KERNEL VERION:** V3.17

**FIRMWARE CHANGES AND ENHANCEMENTS:**

N/A

**MODIFICATIONS:**

Note!! The following Known Issues have been fixed in this release of firmware.

Modify the power limit of POE from 15.4W to 22.6W.

.

**KNOWN RESTRICTIONS AND LIMITATIONS:**

N/A

=====

**Software Release Note**

=====

**RELEASE DATE:** 22-Jan-2010  
**FIRMWARE VERSION:** V1.07  
**KERNEL VERION:** V2.77

**FIRMWARE CHANGES AND ENHANCEMENTS:**

N/A

**MODIFICATIONS:**

Note!! The following Known Issues have been fixed in this release of firmware.

For X-ring:

1. Modify X-ring BPDU DA Mac address from 01-80-C2-00-00-0E to 01-80-C2-00-00-09.
  2. Increasing stability of X-ring, we Modify and enhance the X-ring BPDU priority, so that CUP can process X-ring BPDU first than other packets at the same time.
- .

**KNOWN RESTRICTIONS AND LIMITATIONS:**

N/A

=====

**Software Release Note**

=====

**RELEASE DATE:** 01-Oct-2009  
**FIRMWARE VERSION:** V1.07  
**KERNEL VERION:** V2.46

**FIRMWARE CHANGES AND ENHANCEMENTS:**

N/A

**MODIFICATIONS:**

*Note!! The following Known Issues have been fixed in this release of firmware.*

Customzation for Transition SM8TXAF2GPA, Add DA/SA/VTU priority in QoS.

**KNOWN RESTRICTIONS AND LIMITATIONS:**

N/A

**KNOWN ISSUES:**

*Note!!The following Known Issues will fix in the further release of firmware.*

N/A

=====  
**Software Release Note**  
=====

**RELEASE DATE:** 20-May-2009  
**FIRMWARE VERSION:** V1.07  
**KERNEL VERION:** V2.00

**FIRMWARE CHANGES AND ENHANCEMENTS:**

N/A

**MODIFICATIONS:**

*Note!! The following Known Issues have been fixed in this release of firmware.*

Add Q-in-Q function into this version.

**KNOWN RESTRICTIONS AND LIMITATIONS:**

N/A

**KNOWN ISSUES:**

*Note!!The following Known Issues will fix in the further release of firmware.*

N/A