



S3240 Release Notes

Date: December 10, 2013

Version: 1.0.2

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the S3240 product.

Management of the S3240 is available using a web browser or Command Line Interface (CLI) via the local USB port or telnet of the S3240 or via SNMP.

Requirements:

Firmware version 1.0.2 and these release notes apply to the following products:

- S3240

New Features and Fixes:

The following list is a list of new features and bugs fixed in firmware version 1.0.2.

- Added ability to switch active/standby port via SNMP and CLI for redundant mode

MIB:

Setting `ionIfRedundActivePort` to 0, the redundancy active port will be switched.

The description of `ionIfRedundActivePort` is updated to declare “0” means switch the redundancy active port.

CLI:

CLI command “set redundancy switch” is added.

Known Feature Limitations:

The following list is currently known issues for the S3240.

- Web interface and CLI are different for FNG alarm time and FNG reset time
- RADIUS server secret is not backed up in configuration backup & restore

Related Documentation:

- S3240 User Guide (33459)
- ION Command Line Interface Reference Guide (33474)

MIBs:

- S3240_MIB.zip file