



---

## S3280 Family Release Notes

**Date: Oct 21, 2013**

**Version: 1.7.4**

---

### Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the S3280 and S3280-TST product families.

Management of the S3280 and S3280-TST is available using Converge™ EMS, SNMP, Web or Command Line Interface (CLI) locally or via Telnet.

### Requirements:

Firmware version 1.7.4 and these release notes apply to the following products:

- S3280
- S3280-TST

### New Features and Enhancements:

The following is a list of new features and enhancements for version 1.7.4

### Fixes in 1.7.4

- Fix to use MAC address in DHCP option 61 client-identifier

### Known Feature Limitations:

The following is a list of currently known issues for the S3280.

- MEPs do not work over ports using link aggregation
- L2CP settings are in the CLI only and not Web interface

### Related Documentation:

- S3280 User Guide (33506)
- S3280 CLI Reference Guide (33507)
- RFC 2544 User Guide (33540)
- Static IP Routing User Guide (33542)

### MIBs:

- TNMIBs\_1.7.4.zip file