



## **DataBand IMUX Release Notes**

**Date: July 24, 2013**

**Version: Vb8.55**

### **Overview**

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the DataBand IMUX product.

Management of the DataBand IMUX is available using DbManager.

### **Requirements:**

Firmware version Vb8.55 and these release notes apply to the following products:

- DB-ISU-1024-1P-AC
- DB-ISU-2U2SBRI-AC
- DB-ISU-512-1P-AC
- DB-ISU-512-4S-AC
- DB-ISU-512-4U-AC

### **New Features and Enhancements:**

- None

### **Bug Fixes:**

- Software continuously tries to enable layer 2 when Permanent Link for BRI is checked. Addresses issue where DataBand IMUX would attempt to establish BRI connection before the layer 2 network was active.

### **Related Documentation:**

- DataBand IMUX User Manual