



Transition Networks
10900 Red Circle Drive
Minnetonka, MN 55343
www.transition.com

SISGM1040-184D-LRT Release Notes

Date: Mar.14, 2017

Version: 1.00.01

Overview

This release notes covers firmware version v1.00.01 for SISGM1040-184D-LRT.

Release Changes and Enhancements

1. The Configure menu is missing the "Loop Protection" item.
2. Page headings can overlap when text is expanded. This is especially apparent on the page for DHCP bindings
3. There is no Log-Out button or function on the web GUI.
4. The switch crashes when Tacacs+ is enabled on HTTP with the 2nd method set to Local.
5. The left side navigation tree can be expanded with the "Open All" button but there is no way to close or collapse the tree
6. There are CLI commands that crash the switch

Known Limitations and Restrictions

Now the logout function still has issue for using IE browser, but Chrome is fine.