



SISPM1040-382-LRT Release Notes

Date: Jan 19, 2017

Version: 1.33

Overview

This release notes covers firmware version 1.33 for SISPM1040-382-LRT.

Release Changes and Enhancements

1. Fix provided for issue where a MIB walk was still allowed using SNMP default community strings (public/private) even though it was changed from default on the device.
2. Fix provided for issue where device failed to pass the NMAP intense scan/McAfee failure and device lost management when scanned.

Known Limitations and Restrictions

1. EAP MD5 must be set as the default authentication method on any Radius server. This applies to Radius servers such as FreeRadius which may accept MD5 and have TLS as the default setting in EAP configuration.