

Lantronix, Inc. 12755 Highway 55, Ste H100 Plymouth, MN 55441 www.lantronix.com

ION x4110-4848 Release Notes

Date: February 7, 2023

Version: v2.0.5

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the ION C4110-4848 and S4110-4848 products.

The C4110 supports remote management when it is installed in a managed ION chassis. Through the IONMM, management is available using a web browser or Command Line Interface (CLI) via the local USB port or telnet. Management is also available via SNMP.

Requirements:

Firmware v2.0.5 and these release notes apply to the following products:

- C4110-4848
- S4110-4848

New Features and Enhancements:

The following enhancements are incorporated into firmware v2.0.5:

• Adjustments to allow sufficient time for checking link status and sending traps

Related Documentation:

- ION C4110-4848 User Guide (33572)
- ION S4110-4848 User Guide (33573)
- ION219-x 19-slot Chassis Install Guide (33412)
- ION Management Module Installation Guide (33420)
- ION Management Module User Guide (33457)
- ION Command Line Interface Reference Guide (33461)

Known Limitations:

 There is currently no CLI command available for Port Link Status; port link status can be viewed in web UI