

ION x3100-4040 Release Notes

Date: August 14, 2023

Version: v2.0.3

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the C3100-4040.

Firmware V2.0.3 and these release notes apply to the following products:

- C3100-4040
- S3100-4040

Requirements:

Management of the C3100-4040 is available using the Web UI on a desktop or laptop with Windows OS or Linux distro or Command Line Interface (CLI) via the console port on the IONMM or SSH when installed in an ION chassis. C3100 and S3100 do not support remote management when they are deployed as remote stand-alone converters. The x3100 devices do not support remote in-band management over fiber, even when the remote unit is linked back to a local unit installed in a managed ION chassis.

New Features and Enhancements:

This release includes the following enhancements:

- Fixed issue causing port 2 DMI information not to appear when an SFP is not present in port 1.

Related Documentation:

- ION C3100 Install Guide (33580)
- ION S3100 Install Guide (33581)
- ION System x3100 Series Web User Guide (33582)
- ION System x3100 Series Command Line Interface Reference Manual (33583)

Known Limitations:

- none