



---

## SISPM1040-3248-L and SISPM1040-3166-L Release Notes

**Date: Mar.22, 2021**

**Version: 8.50.0018**

---

### Overview

This release notes covers firmware version v8.50.0018 and MIB files for SISPM1040-3248-L and SISPM1040-3166-L

### Release Changes and Enhancements

#### [New Features & Changes]

=====

- \* Rename "Soft Reboot" to "Always On PoE".

#### [Bugs Fixed]

=====

- \* MRP: Pull out cable, MRP\_Ring state show "unknown".
- \* API: Can't get PoE firmware version via API.  
=> To add the "PoE Firmware Version" data in the API /api/get\_poe\_config
- \* API: No "profile selection" is provided when using API /api/get\_poe\_config to get PoE schedule.
- \* The description of QCE ipv6 is wrong.
- \* API: User get wrong information via /api/get\_firmware\_upgrade\_status API.
- \* No response from API if changing IP address.
- \* MIB: Failed to get the SystemInfoProductionDate value but got the unparsed mib node.
- \* Backup Configuration : Backup Configuration provide download "api\_translater.st".
- \* LLDP : PMD Auto-Negotiation Advertised Capability field does not display all the available speeds of the port.

### Known Limitations and Restrictions

1. ERPS: UP MEP is not supported for sub-ring