
SISPM1040-3166-L3 Release Notes**Date: May 23, 2024****Version: 8.10.0105**

Overview

This release note covers firmware version 8.10.0105 and Mib files for SISPM1040-3166-L3.

Release Changes and Enhancements

- Updated ConsoleFlow to Percepixon.

Bugs Fixed

- Addressed issue when SISPM1040-3166-L3 is configured as master rule in Rapid-Ring (single-ring), the PC connected on the SISPM1040-3166-L3 can't ping to other ring member switches.
- Addressed issue when SISPM1040-3248-L3 is configured as master rule in Rapid-Ring (multi-ring), the PC connected on the SISPM1040-3166-L3 can't ping to other ring member switches.
- Missing connection information in the running-config.

Known issues

- None