
SISPM1040-582-LRT Release Notes**Date: September 26, 2022****Version: B7.20.0121**

Overview

This release note covers firmware version B7.20.0121 and Mib files for SISPM1040-582-LRT.

Release Changes and Enhancements

Radius server configuration “key words” encrypted in the Web.

Support DHCP per port function can select a particular IP interface.

Default setting updates:

- = SNMP mode stays Disabled as factory default.

- = Activate First time wizard mechanism.

- = Auth Method Configuration.

Added Support for DHCP option 229.

Added encryption in Firmware file.

Added ConsoleFlow Cloud support

Bugs Fixed

RADIUS Server Configuration page click Apply twice; radius-server key will be cleared in GUI.

TACACS+ Server Configuration page click Apply twice; tacacs-server host will be cleared in GUI.

Web: To execute Advanced Scan via Nessus, will cause the DUT to crash and restart.

Known issues

VLAN 1 cannot be deleted via WebUI

ERPS failover sometimes exceeds 50ms