

**SISPM1040-582-LRT Release Notes****Date: March 10, 2026****Version: vB7.20.0254**

---

**Overview**

These release note covers firmware version vB7.20.0254 and MIB files for model SISPM1040-582-LRT.

**New Features**

- Disabled TLS 1.0 and 1.1; active version is TLS 1.2. Ensure web browser is up to date.

**Bugs Fixed**

- Press RESET button to default will display error message on CLI.
- Switch is accepting HTTP requests on port 80 even after creating ACL rule to deny HTTP traffic.

**Known Limitations**

- None