

SM12DP2XA Release Notes**Date: September 30, 2024****Version: v7.20.0206**

Overview

These release note covers firmware version v7.20.0206 and MIB files for model SM12DP2XA.

Bugs Fixed

- Perception server now shows error message when wrong firmware is uploaded
- Fixed incorrect voltage value on Perception server telemetry page
- Resolved timing issue with Perception telemetry exchanges

Known Limitations

- Rapid Ring roles cannot be returned to Disable using the Web GUI. The roles can be disabled using the CLI command interface.
- Web timeout has issue with timeout set greater than 10 minutes.