



SM24TBT2DPA Release Notes

Date: May.19, 2020

Version: vB6.54.3476

Overview

This release notes covers firmware version vB6.54.3476 and MIB file for SM24TBT2DPA.

Release Changes and Enhancements

[Add and Change]

*Modified PoE 802.3bt FW version

- Actively send BT version of Power Via MDI TLVs.
- Reply with AT version of Power Via MDI TLV if PD is using such version of TLV, and additionally send 2 more BT TLVs.

* Add Device list table & API.

* DHCP pool per VLAN request.

* Add a field to show Aggregated Bandwidth information on Link Aggregation feature.

* modify topology view right side function key design.

* Add Click Save Button when Save Start Button on Web UI.

[Bugs Fixed]

* API: Unable to get /stat/dev_list_table information via post man.

* SW: Upgrade poe mcu fw v3.52 will cause the switch to freeze.

* Unable to display the DHCP Server VLAN Range on WebUI.

* Web: Message "CCC" pops up after logging out of WebUI.

* CLI: Show aggregation does not include Speed.

* PoE: When Non-stop-poe is enabled, execute warm boot will cause PoE Disabled.

* CLI: PoE Mode has a redundant command enable to set.

Known Limitations and Restrictions

The switch is not allowed to downgrade to old firmware versions due the PoE MCU firmware is upgraded in vB6.54.3476.