



---

## SM48TAT4XA-RP Release Notes

**Date: Sep.14, 2020**

**Version: 8.40.1845**

---

### Overview

This release notes covers firmware version v8.40.1845 and MIB file for SM48TAT4XA-RP

### Release Changes and Enhancements

#### [New Features & Changes]

=====

- \* Timeout expected behavior.
- \* Add a field to show Aggregated Bandwidth information on Link Aggregation feature.
- \* Modify System Information Name display requirement.

#### [Bugs Fixed]

=====

- \* Switch crash if DMS master changes frequently.
- \* Reflash the Web GUI, the Timeout setting will be returned to the value in Startup Config setting.
- \* LACP System Status and Aggregation Status information display error.
- \* LACP: Setting Static Aggregation Group, the Aggregation Status does not have any information.
- \* Web: If modifying System name, the Model name will be affected.

### Known Limitations and Restrictions

N/A