

---

**SM48TAT4XA-RP Release Notes****Date: November 21, 2022****Version: v8.50.0079**

---

**Overview**

This release note covers firmware version 8.50.0079 and Mib files for SM48TAT4XA-RP models.

**Release Changes and Enhancements**

- Added support for DHCP per port function. Can select a particular IP interface.
- Added support for additional PoE controllers
- Updated jQuery to version 3.6.0
- Updated default settings
  - SNMP mode stays Disabled as factory default.
  - Activated first time wizard mechanism that requires password change on initial login
  - Added Auth Method Configuration.

**Bugs Fixed**

DUT cannot traceroute IPv6 in WebUI.

Cannot modify Privilege Levels of Security(access) and Security(network) via Web UI.

SNMP no response when performing getbulk with oid 1.3.6.1.2.1.55.1.8.1.2

Digital I/O of Event Notification on Web UI's menu, but the web show incorrect path Home>Configuration>System>Digital I/O.

Using BCM59011 PoE's chip, show incorrect PoE version "000-000".

The boot will show message vtss\_ici\_parsing\_build/vtss\_ici\_register\_cmd/ici\_config\_ici\_cmd\_register Error in CLI.

Set cmd "ip link-local interface 2" and save, after reboot DUT will show "VLAN ID 2 is not existed. Please create it and set its IP." in CLI.

**Known issues**

- None