

IMPORTANT NOTE: Due to the integration of the single boot and dual boot firmware patches into a single patch, if you are running firmware older than 5.0, please upgrade your unit to version [5.2a](#) of your respective boot type prior to applying the 5.3 update.

Firmware update file slcupdate-db-5.3.tgz or higher can then be used to update any single or dual boot SLC to 5.3 or higher.

[Click here for information on loading v5.2a.](#)