

Firmware Release Notes

NTC-140-01



Copyright

Copyright© 2018 NetComm Wireless Limited. All rights reserved.

The information contained herein is proprietary to NetComm Wireless. No part of this document may be translated, transcribed, reproduced, in any form, or by any means without prior written consent of NetComm Wireless.

Trademarks and registered trademarks are the property of NetComm Wireless Limited or their respective owners. Specifications are subject to change without notice. Images shown may vary slightly from the actual product.



Note – This document is subject to change without notice.

Document history

Ver.	Document description	Date
v1.0	Initial document release	9 March 2018

Table i. - Document revision history

Release information

Item	Details
Model Number	NTC-140-01
Router Firmware Version	2.0.23.19
Firmware file name	vzw_140ng_2.0.23.19.cdi MD5: 93d02388e7cca419790351626efe4
Date	9 March 2018



Release history

v2.0.23.19 (Initial firmware release for technical approval)

New Features/Changes

-  Removed the WiFi and GPS features.

Enhancements

-  TT#21441: Corrected an SDK issue where a ulmage could not be generated because of a missing variant in the Linux kernel (vi linux/kernel/timeconst.pl)
-  TT#21518: Corrected an SDK issue where after installing ulmage, the device could not complete the reboot process.