



IONPS-A & IONPS-D Release Notes

Date: October 25, 2021

Version: 1.2.9

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the power supply modules used in the ION 19-slot chassis.

Requirements:

Firmware version 1.2.9 and these release notes apply to the following products:

- IONPS-A ION AC power supply module for the 19-slot chassis
- IONPS-D ION DC power supply module for the 19-slot chassis

New Features and Enhancements:

The following is a list of new features and enhancements in version 1.2.9 of the IONPS-A and IONPS-D:

- Includes a fix for a dry contact relay issue

Known limitations:

- When using the IONMM v1.4.3 or earlier to manage the IONPS-A and IONPS-D, Back-up and Restore features are not functional
 - This limitation will no longer apply with the soon to be released IONMM Firmware (expected to be v1.5.0)

Related Documentation:

- ION219-x User Guide (33412)
- IONPS-A User Guide (33423)
- IONPS-D User Guide (33424)