



Transition Networks  
10900 Red Circle Drive  
Minnetonka, MN 55343  
[www.transition.com](http://www.transition.com)

---

## **SISPM1040-384-LRT-B Release Notes**

**Date: Apr.7, 2017**

**Version: 1.30\_k10.08**

---

### **Overview**

This release notes covers firmware version v1.30\_k10.08 for SISPM1040-384-LRT-B.

### **Release Changes and Enhancements**

[Fixed]

1. Port Alias description did not save in restore config
2. No help file in Port Alias page view
3. No logout icon in Web GUI
4. Remove ALL EVC field

### **Known Limitations and Restrictions**

N/A