

Transition Networks 10900 Red Circle Drive Minnetonka, MN 55343 www.transition.com

SM24DPB Release Notes Date: Jun.6, 2016 Version: 6.46.1860

Overview

This release notes covers firmware version v6.46.1860 for SM24DPB.

Release Changes and Enhancements

Firmware Version: v6.46.1860 [Modification]

* Change the default configuration of Bonjour Discovery to disabled.

[Fixed]

- * Add online Help for the Bonjour Discovery.
- * Sflow configuration will be reset when timeout value is counting to 0.
- * Modify the save configuration can't be executed during firmware upgrade to avoid flash read/write conflict.
- * DHCP Server Global mode will be disabled when changing gateway IP from DMS page.
- * When DMS enable, VLAN port role will be changed when the port state becomes link down.

Known Limitations and Restrictions

N/A